

Figure 1A




Figure 1B




Figure 1C

Figure 1C is a schematic diagram of a curved member, such as a bone, showing various points and regions. The member is oriented diagonally from the bottom-left to the top-right. A dashed line 34 outlines a region at the bottom-left end. A dashed line 42 outlines a region at the top-right end. A solid line 26 represents the main body of the member. A dashed line 32 represents an alternative or boundary shape. A point L.P. (Lower Point) is marked on the lower part of the member. A point U.P. (Upper Point) is marked on the upper part of the member. A point A.L.P. (Anterior Lower Point) is marked on the lower part of the member. A point A.U.P. (Anterior Upper Point) is marked on the upper part of the member. A curved line C.C. (Curvature Center) is shown near the center of the member.

[illegible]

Figure 1E

